



TDK Corporation

HHM1596A1


Part Number: HHM1596A1
 Manufacturer/Brand: TDK Corporation
 Product description: BALUN 3.1GHZ-4.9GHZ 50/100 0805
 Datasheets: [PDF HHM1596A1.pdf](#)
 RoHs Status:  Lead free / RoHS Compliant
 Ship From: Hong Kong
 Shipment Way: DHL/Fedex/TNT/UPS/EMS



Image may be representation. See specifications for product details.

[REQUEST FOR QUOTATION](#)













Specifications of HHM1596A1

PART NUMBER	HHM1596A1
MANUFACTURER	TDK Corporation
DESCRIPTION	BALUN 3.1GHZ-4.9GHZ 50/100 0805
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
DATA SHEET	PDF HHM1596A1.pdf
SERIES	HHM
RETURN LOSS (MIN)	10dB
PHASE DIFFERENCE	180° ±15°
PACKAGING	Tape & Reel (TR)
PACKAGE / CASE	0805 (2012 Metric)
OTHER NAMES	445-3386-2
MOUNTING TYPE	Surface Mount
MOISTURE SENSITIVITY LEVEL (MSL)	1 (Unlimited)
MANUFACTURER STANDARD LEAD TIME	12 Weeks
LEAD FREE STATUS / ROHS STATUS	Lead free / RoHS Compliant
INSERTION LOSS (MAX)	1.0dB
IMPEDANCE - UNBALANCED/BALANCED	50 / 100 Ohm
FREQUENCY RANGE	3.1GHz ~ 4.9GHz
DETAILED DESCRIPTION	RF Balun 3.1GHz ~ 4.9GHz 50 / 100 Ohm 0805 (2012 Metric)

Related Tags

TDK Corporation HHM1596A1	HHM1596A1 Distributor	HHM1596A1 Supplier
HHM1596A1 Price	HHM1596A1 Pictures	HHM1596A1 Image
HHM1596A1 PDF Datasheet	HHM1596A1 Download Datasheet	HHM1596A1 Datasheet
HHM1596A1 Stock	Buy HHM1596A1	Buy TDK Corporation HHM1596A1
TDK Corporation HHM1596A1	TDK Corporation Supplier	TDK Corporation Distributor
TDK Corporation HHM1596A1		

Related Products

 <p>HHM1711E1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 In stock: Out stock RFQ</p>	 <p>HHM1570B1 Manufacturers: TDK Corporation Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805 In stock: Out stock RFQ</p>
 <p>HHM1591D1 Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM1711D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 In stock: 503 pcs RFQ</p>
 <p>HHM1595A1 Manufacturers: TDK Corporation Description: BALUN 3GHZ-8GHZ 50/100 0805 In stock: Out stock RFQ</p>	 <p>HHM17125D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ</p>
 <p>HHM1710D1 Manufacturers: TDK Corporation Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 In stock: Out stock RFQ</p>	 <p>HHM1589E1 Manufacturers: TDK Corporation Description: BALUN 350MHZ-470MHZ 50/200 0805 In stock: Out stock RFQ</p>
 <p>HHM1603A1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-2.7GHZ 50/100 4SMD In stock: Out stock RFQ</p>	 <p>HHM1583B1 Manufacturers: TDK Corporation Description: BALUN 3.1GHZ-4.9GHZ 50/100 0805 In stock: Out stock RFQ</p>
 <p>HHM1711Q1 Manufacturers: TDK Corporation Description: BALUN 2.3GHZ-3.8GHZ 50/100 0603 In stock: Out stock RFQ</p>	 <p>HHM1589B1 Manufacturers: TDK Corporation Description: BALUN 470MHZ-710MHZ 6SMD In stock: Out stock RFQ</p>